



Re: Roof Consulting Services, Inc. of Texas

May 19, 2009

To Whom It May Concern:

I had Mark Fulfer of Roof Consulting Services inspect our Church Roof and prepare Specifications for replacement of our 66,700 sq. ft. leaking (40 plus leaks), ballasted EPDM Single Ply Roof. We were very disappointed in the poor performance we received from the EPDM System as we had leaks on it continuously almost from day one and actually had to completely replace it about two years after it was installed. It was very susceptible to leaks from punctures, normal foot traffic and seams and laps that would open up. I have experience in several facilities with single ply and Modified roof systems and would at this point not even consider ever using single ply systems again because of very poor performance. Our brand new BUR/Modified Bitumen roof withstood 60 mph plus winds and still looks brand new almost 1 year after installation.

Mark prepared Specifications for a BUR/Modified Bitumen Hybrid System and gathered competitive bids from his network of approved Contractors for us. The job was smooth, quick and professionally conducted. Mark was there to oversee all phases of the job and document it for our records. Their approach is unique and effective, unlike any of the other Roof Consultants or Contractors I have dealt with in the past.

I would highly recommend Mark Fulfer, Roof Consulting Services, Inc. of Texas and their network of Contractors to anyone that wants their roof problems solved permanently.

Sincerely,

A handwritten signature in black ink that reads "Robert Barley". The signature is written in a cursive style with a long, sweeping underline.

Robert Barley
Facilities Manager
North Fort Worth Baptist Church
5801 North I-35 W
Fort Worth, Texas 76131
817-232-8210 X 117 church
817-229-4827 cell
RobertBarley@NorthFortWorth.com